

## **DS-9000/DS-2600 Firmware Release Ver.1.025**

### 1. New Firmware Version

Ver1.025 ( It will be disclosed as Version 1.02 to the customers.)

### 2. Content

Firmware bug fix.

### 3. Contents to be disclosed to customers.

Fixed the issue that when playback a file recorded with VCVA mode, it may not be able to playback normally from the middle.

### 4. Phenomenon

The following phenomenon may occur when playback a file recorded with VCVA mode.

- When playback a specific file on the device, it may skip to the file end during file playback.

- When playback a specific file with ODMS, it may be cases where an abnormal sound occurs during file playback.

### 5. Cause

If it becomes standby at a specific timing during recording with VCVA mode, recording data may be written to the file management data area.

### 6. Measures

Changed to buffer recording data and file management data in separate areas.

### 7. Release Schedule April 2, 2019

<Contents of release>

- Win version updater for DS-9000 and DS-2600.

- Mac version updater for DS-9000 and DS-2600.